


A. Washer.

Step 1. Click File Menu > New, click **Part Metric** and OK.

Step 2. Click **Right** (plane) in the Feature Manager and click **Sketch**  from the Content toolbar, **Fig. 2**.




Fig. 2

Step 3. Click **Circle**  (S) on the Sketch toolbar.

Step 4. Draw two circles starting at the Origin , **Fig. 2**.

Step 5. Click **Fully Defined Sketch**  (D) on the Sketch toolbar and OK  in the Property Manager.





Fig. 2

Step 6. Dimension the circles as shown in **Fig. 3**.

Step 7. Click **Features**  on the Command Manager toolbar.






Fig. 3

Step 8. Click **Extruded Boss/Base**  on the Features toolbar.

Step 9. In the Property Manager, under **Direction 1** set:

End Condition to **Mid Plane**
 Depth  to **.8**
 and click OK , **Fig. 4** and **Fig. 5**.




Fig. 4




Fig. 5


B. Save as "WASHER".

Step 1. Click File Menu > Save As.

Step 2. Key-in **WASHER** for the filename and press ENTER.

C. Appearance.

Step 1. Click Edit Menu > Appearance > Material.

Step 2. Scroll down the Materials and **Copper and its Alloys**, **Fig. 6**. Select **Brass** and click OK .

Step 3. Save. Use **Ctrl-S**.




Fig. 6



Fig. 7