


Belt Buckle




A. Create Rectangle.

Step 1. If necessary start a new Mastercam file, click

New  (Ctrl-N) on the Quick Access Toolbar QAT.

Step 2. On the Wireframe tab **WIREFRAME** click **Rectangle**



Step 3. In the Rectangle function panel:

under Dimensions, **Fig. 1**

Width 4

Height 3 and press ENTER

Press **spacebar** to activate Fast Point 

Key-in **.5, 0**  and press ENTER **twice**

Click OK .




Fig. 1

Step 4. **Right click** the graphics window and click **Fit**



Step 5. Use **F9** to toggle Origin/Axis display on and off to confirm Origin, **Fig. 2**.

B. Save As "BELT BUCKLE"

Step 1. Click **Save As**  (Ctrl-Shift-S) on the Quick Access Toolbar QAT.

Step 2. Key-in **BELT BUCKLE** for the file-name and press ENTER.





Fig. 2

C. Create Ellipse.

Step 1. On the Wireframe tab **WIREFRAME** click **Ellipse**  on


Rectangle  drop down.

Step 2. In the Ellipse dialog box set:

Width  **1.975** **Fig. 3**

Height  **1.25** and press ENTER

Press **spacebar** to activate Fast Point 

Key-in **2.5, 1.5**  and press ENTER

Click OK .




Fig. 3





Fig. 4

D. Offset Ellipse.

Step 1. On the Wireframe tab **WIREFRAME** click

Offset .

Step 2. In Offset dialog box:

under Mode, **Fig. 5**

select **Copy** 

Distance  **.09**

Click **ellipse**, then click **inside**, **Fig. 6**

The purple offset should be inside of the red original.

If it is not, click Reverse button , **Fig. 5**.

Click OK .




Fig. 5

Step 3. **Right click** the graphics window and click **Clear Colors** .

Step 4. Save  (**Ctrl-S**).





Fig. 6

E. Three Circles.

Step 1. On the Wireframe tab **WIREFRAME** click **Circle Center Point**




Step 2. In the Circle Center Point function panel:
under Size, **Fig. 7**


Click **Locked** 

Diameter .159 and press ENTER

Press **spacebar** to activate AutoCursor **Fast Point** 

Key-in **1.2, 1.5, -.25**  and press ENTER

Key-in **3.5, 1.95, -.25**  and press ENTER

Key-in **3.5, 1.05, -.25**  and press ENTER **twice**

Click OK 




Fig. 7

F. Merge Mastercam Graphic File.

Step 1. Download **mastercam-graphic.dxf** from
http://www.cudacountry.net/html/mastercam17_toc.html

Step 2. Back in Mastercam 2017, click File Menu > Merge.

Step 3. In the Open dialog box:
Set **Files of type** to
AutoCAD.DXF, **Fig. 9**
Select the **mastercam-graphic.dxf**
file and click Open.

Step 4. In the Merge Pattern function panel
click OK 




Fig. 8




Fig. 9



Fig. 11





Fig. 10

G. Extrude Outside Ellipse Solid.

Step 1. Change to the Isometric View. **Right click** in the graphics window and click



Step 2. **Right click** in the graphics window and on the Mini Toolbar click **Solid Color** drop down arrow, then click **light cyan**, Fig. 12.





Fig. 12

Step 3. On the Solids tab **SOLIDS** click **Extrude**



Step 4. Click Chain  in Chaining dialog box, Fig. 13.

Step 5. Click **outside ellipse** to chain, Fig. 14.

Step 6. Click OK  in Chaining dialog box.




Fig. 14

Step 7. In the Solid Extrude function panel:
under Operation, Fig. 15
select **Create body**
under Distance

Distance .25 and press ENTER

The direction arrow should **point down**, Fig. 16. If arrow points in wrong direction, click Reverse All , Fig. 15.

Click **OK** and **Create New Operation** .




Fig. 13




Fig. 16




Fig. 15

H. Cut Inside Ellipse.

Step 1. Click Chain  in Chaining dialog box.

Step 2. Click **inside ellipse** to chain, **Fig. 17**.

Step 3. Click OK  in Chaining dialog box.

Step 4. In the Solid Extrude function panel:
under Operation, **Fig. 18**
select **Cut body**
under Distance

Distance .07 and press ENTER

The direction arrow should **point down**, **Fig. 19**. If arrow points in wrong direction, click Reverse All , **Fig. 18**.

Click **OK and Create New Operation** .




Fig. 17




Fig. 18




Fig. 19

I. Extrude Mastercam Solid.

Step 1. **Right click** in the graphics window and on the Mini Toolbar click **Solid Color**  drop down arrow, then click **light red**, Fig. 20.




Fig. 20

Step 2. Click Chain  in Chaining dialog box.

Step 3. Click **each letter** and **include inner geometry of a's and e** in chaining, Fig. 21.

Step 4. Click OK  in Chaining dialog box.

Step 5. In the Solid Extrude function panel:
under Operation, Fig. 22
select **Create body**
under Distance

Distance .07 and press ENTER

The direction arrow should **point down**, Fig. 23. If arrow points in wrong direction, click Reverse All , Fig. 22.

Click **OK** and **Create New Operation** .




Fig. 21




Fig. 22




Fig. 23

J. Cut Holes.

Step 1. Use **Ctrl-T** to toggle **Translucency**.

Step 2. Click Chain  in Chaining dialog box.

Step 3. Click the **3 circles**, Fig. 24.

Step 4. Click OK  in Chaining dialog box.

Step 5. In the Solid Extrude function panel:
under Operation, Fig. 25
select **Cut body**
under Distance

Distance .15 and press ENTER

The direction arrow should **point up**, Fig. 26. If arrow points in wrong direction, click Reverse All , Fig. 25.

Click OK .




Fig. 24




Fig. 25




Fig. 26

Step 6. Turn **off** Shading (**Alt-S**).

Step 7. Use **Ctrl-T** to toggle **Translucency**.

Step 8. Save  (**Ctrl-S**).





Fig. 27

K. Stock Setup.

Step 1. If necessary, display Toolpaths Manager. On the View tab



Step 2. If Machine Group is **not** displayed in the Toolpaths Manager,

Fig. 28 on the Machine tab **MACHINE**, click Machine  > Default from the menu.




Fig. 28

Step 3. Expand **Properties** (click +) in Toolpaths Manager, **Fig. 28**.

Step 4. Click **Stock Setup** in Toolpaths Manager, **Fig. 29**.

Step 5. Click left front top corner of the stock to move the origin, **Fig. 29**. After you click corner the arrow will point to corner.

Step 6. Click **All Entities** in Stock Setup dialog box, **Fig. 29**.

Step 7. Confirm **Display** check box is checked, **Fig. 29**.

Step 8. Click OK  in Machine Group Properties, **Fig. 30**.




Fig. 29




Fig. 30

L. 2D High Speed Dynamic Mill Toolpath.

Step 1. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Dy-**



amic Mill




Fig. 31

Step 2. Click OK  in NC name dialog, Fig. 31.

Step 3. Select **Machining regions**  button in Chain Options dialog box, Fig. 32.

Step 4. Select **Chain**  in Chaining dialog box, Fig. 33.

Step 5. Click the **inside ellipse** to Chain the ellipse and click OK  in Chain dialog box, Fig. 34.




Fig. 34

Step 6. Select **Avoidance regions**  button in Chain Options dialog box, Fig. 35.

Step 7. Click **each letters** to Chain letters (no inner space) and click OK  in Chain dialog box, Fig. 36.

Step 8. Click OK  in Chain Options box, Fig. 35.




Fig. 36




Fig. 32




Fig. 33




Fig. 35

Step 9. Select
Toolpath Type
from the tree
control and
confirm:

Dynamic Mill
toolpath

**Machining
regions 1**

**Avoidance
regions 9**
Fig. 37.

Step 10. Select **Tool**
from tree con-
trol and:
click **Select
library tool**
Fig. 38.




Fig. 37




Fig. 38

Step 11. Click **Filter** in Tool Selection dialog box, **Fig. 39**.

Step 12. Click **None** under Tool Types **Fig. 40**.

Step 13. Click **Endmill1 Flat** button (first button top row) and click OK **Fig. 40**.

Step 14. Click **284 3/16 FLAT ENDMILL** and click OK **Fig. 41**.




Fig. 39




Fig. 40




Fig. 41

Step 15. Back in **Tool** page set:

Tool # 1
Feed rate 200

Plunge rate
100

Fig. 42.

Step 16. Select **Cut Parameters** from tree control and set:

Cutting method
Climb

Stock to leave on walls and floors 0
Fig. 43.




Fig. 42




Fig. 43

Step 17. Select **Depth Cuts** from tree control and set:

Check
Depth cuts

Max rough step .02
Fig. 44.

Step 18. Select **Entry Motion** from tree control and set:

Z clearance .02
Fig. 45.




Fig. 44




Fig. 45

Step 19. Select **Linking Parameters** from tree control and set:

Depth -.07
Fig. 46.

Step 20. Click OK  in Dynamic Mill dialog box.

Step 21. Allow Mastercam to calculate the toolpath.

Step 22. Save  (Ctrl-S).




Fig. 46




Fig. 47

M. 2D High Speed Area Mill Toolpath.

Step 1. Use **Alt-T** to turn off toolpath display.

Step 2. Copy and Paste **Dynamic Mill** toolpath in the Toolpaths Manager. To copy, click to select toolpath, **Fig. 48**. Then, use **Ctrl-C** and **Ctrl-V**, **Fig. 49**.

Step 3. Expand copied toolpath and click **Parameters**, **Fig. 49**.

Step 4. Select **Toolpath Type** from the tree control and select:

Area Mill
Fig. 50.

Step 5. Select **Tool** from tree control and click **Select library tool** **Fig. 51**.




Fig. 48




Fig. 49




Fig. 50




Fig. 51

Step 6. Click **279 1/32 FLAT END-MILL** and click OK **Fig. 52.**

Step 7. Back in **Tool** page set:

Tool # 2

Feed rate 2

Plunge rate 1
Fig. 53.




Fig. 52




Fig. 53

Step 8. Select **Cut Parameters** from tree control and set:

XY stepover
% of dia
45
Fig. 54.

Step 9. Select **Transitions** from tree control and set:

Z clearance
.02
Fig. 55.

Step 10. Click OK  in Area Mill dialog box.




Fig. 54




Fig. 55

N. Verify Two Toolpaths.

Step 1. In the Toolpaths Manager, click **Regenerate all selected operations**



Fig. 56.

Step 2. Save  (Ctrl-S).

Step 3. Click **Toolpath Group-1** in the Toolpaths Manager to select **both** toolpaths, Fig. 57.




Fig. 56




Fig. 57

Step 4. Click **Verify**  in the Toolpaths Manager, Fig. 57.


Step 5. Click **Play**  (R) in VCR bar along bottom of the window, Fig. 58.



Fig. 58

Step 6. Note **Total Time** to run program under Toolpath Info in the Move List panel (**roughly 4 hours**), Fig. 59.

Step 7. Switch back to Mastercam (Alt-Tab).



Move Info	
Toolpath Info	
Feed Length	3263.710
Feed Time	3h 48min 41.29s
Min/Max X	0.250 / 4.369
Min/Max Y	0.250 / 2.644
Min/Max Z	-0.070 / 0.250
Rapid Length	129.277
Rapid Time	0.78s
Total Length	3392.987
Total Time	3h 48min 42.07s
Verbose	

Fig. 59




Fig. 60

0. 2D High Speed Dynamic Mill Toolpath.

Step 1. Use **Alt-T** to turn off toolpath display.

Step 2. Copy and Paste **Dynamic Mill** toolpath in the Toolpaths Manager. To copy, click to select toolpath, **Fig. 61**. Then, use **Ctrl-C** and **Ctrl-V**, **Fig. 62**.

Step 3. Expand copied toolpath and click **Parameters**, **Fig. 62**.

Step 4. Select **Toolpath Type** from the tree control and:

Click both **Remove selected machining chains**



and **Remove selected Avoidance**



chains



Fig. 63.

Step 5. Under **Machining regions**

Click **Select machining chains**



Fig. 64.




Fig. 61




Fig. 62




Fig. 63




Fig. 64

Step 6. Select **Chain**  in Chaining dialog box

Step 7. Click to chain **inner geometry of both a's and e letters**, Fig. 65.

Step 8. Click OK  in Chaining dialog box.

Step 9. Back in the Dynamic Mill dialog box, confirm **3** Machining regions chained, Fig. 66.




Fig. 65




Fig. 66

Step 10. Select **Tool** from tree control and set:

Select **1/32 FLAT END-MILL** in the Tool display window

Feed rate 2

Plunge rate 1
Fig. 67.

Step 11. Select **Entry Motion** from tree control and set:

Z clearance .02
Fig. 68.

Step 12. Click OK  in Dynamic Mill dialog box.




Fig. 67




Fig. 68

P. Verify 3 Toolpaths.

Step 1. In the Toolpaths Manager, click **Regenerate all selected operations**



, Fig. 69.

Step 2. Save  (Ctrl-S).

Step 3. Click **Toolpath Group-1** in the Toolpaths Manager to select **all 3** toolpaths, Fig. 70.

Step 4. Click **Verify**  in the Toolpaths Manager, Fig. 70.

Step 5. Click **Play**  (R) in VCR bar along bottom of the window.

Step 6. Switch back to Mastercam (Alt-Tab).




Fig. 69




Fig. 70




Fig. 71

Q. Contour Toolpath with Tab.

Step 1. Use **Alt-T** to turn off toolpath display.

Step 2. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Contour**



Step 3. Click **Chain**  (C) in Chaining dialog box, **Fig. 72**.

Step 4. Click **outside ellipse** to Chain, **Fig. 73**. The chain arrow should point **clockwise** around the chain. If chaining directions arrow is pointing in the opposite direction - click Reverse , **Fig. 72**.

Step 5. Click OK  in Chaining dialog box.




Fig. 73




Fig. 72

Step 6. In the 2D Toolpaths Contour dialog box confirm **1 Chain** is selected, **Fig. 74**.




Fig. 74

Step 7. Select **Tool** from tree control and set:

Select **3/16 FLAT END-MILL** in the Tool display window

Feed rate 200

Plunge rate 100

Fig. 75.

Step 8. Select **Cut Parameters** from tree control and set:

Compensation type Wear

Compensation direction Left

Tip comp: Tip

Stock to leave on walls and floors 0

Fig. 76.




Fig. 75




Fig. 76

Step 9. Select **Depth Cuts** from tree control and set:

Check **Depth cuts**

Max rough step: .02

Finish step 0
Fig. 77.

Step 10. Select **Lead In/Out** from tree control and set:

Uncheck **Lead In/Out**
Fig. 78.




Fig. 77




Fig. 78

Step 11. Select **Tabs** from tree control and set:

Check **Tabs**
Select **Auto-**
matic
Fig. 79.

Step 12. Select **Linking Parameters** from tree control and set:

Depth -.25
Fig. 80.

Step 13. Click OK



Step 14. Save  (Ctrl-S).




Fig. 79




Fig. 80

R. Verify Contour with Tab.

Step 1. Click **Toolpath Group-1** in the Toolpaths Manager to select **all 4** toolpaths, **Fig. 81**.

Step 2. Click **Verify**  in the Toolpaths Manager, **Fig. 81**.

Step 3. Click **Play**  (R) in VCR bar.

Step 4. Switch back to Mastercam (Alt-Tab).




Fig. 82




Fig. 81

S. Create WCS BOTTOM CUT.

Step 1. Rotate view to view **bottom of solid with single hole on left side**, hold down middle mouse button (wheel) and drag to rotate view, **Fig. 83**.

Step 2. Display the **Planes Manager** (**Alt-L**).

Step 3. In the Planes Manager:

Click **Create a new plane**  drop down and select **From geometry**, **Fig. 83**.




Fig. 83

Step 4. Click the **2 lines** in left corner to define construction plane, **Fig. 85**.




Fig. 85




Fig. 84

Step 5. Rotate axes by clicking the arrow in the Select plane dialog box, **Fig. 86** until **X axes points to right, Y axes to rear and Z up**, **Fig. 87**. This should be **Plane 6**, **Fig. 86**.

Click OK  in the Select plane dialog box.



Fig. 86




Fig. 87

- Step 6. In the New Plane dialog box:
 Key-in **BOTTOM CUT** for name, **Fig. 88**
Origin X 0
Origin Y -3
Origin Z .25
 Click OK .




Fig. 88

- Step 7. Back in the Planes Manager:
 Click **Set All** , **Fig. 89**.




Fig. 89

- Step 8. Change to the Isometric View.
Right click in the graphics window
 and click  **Isometric (WCS)** (Alt-7).

- Step 9. Save 
 (Ctrl-S).




Fig. 90

T. Circle Mill Toolpath.

Step 1. Confirm origin.
Use **F9** to toggle axes, **Fig. 91**.

Step 2. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Expand gallery** button and click **Circle Mill** **Fig. 92**.

BOTTOM CUT origin




Fig. 91

Step 3. Click **Entities** button in Drill Point Selection dialog box, **Fig. 93**.

Step 4. Click the **3 circles** and click **End Selection** (ENTER), **Fig. 94**.




Fig. 92

Step 5. Click **OK** in the Drill Point Selection dialog box.




Fig. 93




Fig. 94

Step 6. Select **Tool** from tree control and click **Select library tool** **Fig. 95.**

Step 7. Select **282 1/8 FLAT END-MILL** and click OK **Fig. 96.**




Fig. 95




Fig. 96

Step 8. Back in **Tool** page set:

Tool # 3

Feed rate 2

Plunge rate 1
Fig. 97.

Step 9. Select **Cut Parameters** from the tree control and set:

Compensation type Computer

Compensation direction Left

Tip comp: Tip

Stock to leave on walls and floors 0
Fig. 98.




Fig. 97




Fig. 98

Step 10. Select **Depth Cuts** from the tree control and set:

Check **Depth cuts**

Max rough step: .02
Fig. 99.

Step 11. Select **Linking Parameters** from the tree control and set:

Depth -.15
Fig. 100.

Step 12. Click OK



Step 13. Save  (Ctrl-S).




Fig. 99




Fig. 100

U. Verify Circle Mill.

Step 1. Click **Verify**  in the Toolpaths Manager, **Fig. 101**.

Step 2. Click **Play**  (R) in VCR bar.

Step 3. Switch back to Mastercam (Alt-Tab).




Fig. 102




Fig. 101

V. Change Back to Top WCS.

Step 1. In the Planes Manager (Alt-L) set:
under Name, **Fig. 103**

Click **Top**

Click **Set All** .

Step 2. Change to the Isometric View. **Right click** in the graphics window and click  **Isometric (WCS)** (Alt-7).

Step 3. Save  (Ctrl-S).




Fig. 103