


Cudacountry Radial Toolpaths

A. Stock Setup.

Step 1. If necessary, open your Cudacountry Radial file.

Step 2. If necessary, display Toolpaths Manager. On the View tab



Step 3. If Machine Group is **not** displayed in the Toolpaths Manager,

Fig. 1, on the Machine tab **MACHINE**, click Machine



Default from the menu.




Fig. 1

Step 4. Expand **Properties** (click +) in Toolpaths Manager, **Fig. 1**.

Step 5. Click **Stock Setup** in Toolpaths Manager, **Fig. 1**.

Step 6. Click **left front top corner** of the stock to move the origin, **Fig. 2**. After you click corner the arrow will point to corner.

Step 7. Click **All Entities** in Stock Setup dialog box, **Fig. 2**.

Step 8. Set **X dimension 1.8**, **Fig. 2**.

Step 9. Confirm **Display** check box is checked, **Fig. 2**.

Step 10. Click OK  in Machine Group Properties, **Fig. 3**.




Fig. 2




Fig. 3

B. OptiRough Toolpath.

Step 1. On the Toolpaths tab **TOOLPATHS** in the 3D group click

OptiRough






Fig. 4

Step 2. Click OK  in the NC name dialog, **Fig. 4**.

Step 3. Click the **surface** to select as Drive Surfaces and click **End Selection**  (**ENTER**), **Fig. 5**.

Step 4. Click **Containment Select** button  in the Toolpath/surface selection dialog box, **Fig. 6**.

Step 5. Select **C-plane** in the Chaining dialog box, **Fig. 7**.

Step 6. Click **Chain** button  in the Chaining dialog box, **Fig. 7**.

Step 7. Click a **line of top rectangle** to chain the top rectangle, **Fig. 8**. Click the OK button  in the Chaining dialog box.

Step 8. Click OK  in the Toolpath/surface selection dialog box, **Fig. 9**.




Fig. 5

Containment chain rectangle




Fig. 8




Fig. 6




Fig. 7




Fig. 9

**OptiRough
toolpath
Drive surfaces
and
Containment
Fig. 10.**

click **Select library tool** button, **Fig. 11.**



Step 11. Click the **Filter** button,
Fig. 12.

Step 12. Click **None**
button
under Tool
Types,
Fig. 13.

Step 13. Click **Endmill2 Sphere**
button second button top
row), **Fig. 13** and click OK.

Step 14. Click **304 1/8 Ball End-**
mill, Fig. 14 and click OK.




Fig. 12




Fig. 13




Fig. 14

Step 15. Back in Tool page set:

**Feed rate 40
Plunge rate 20
Fig. 15.**

Step 16. Select **Stock to leave** from the tree control and set:

**Leave stock on Drive walls and floors
.03
Fig. 16.**




Fig. 15




Fig. 16

Step 17. Select **Cut Parameters** from the tree control and set:

Cutting method Climb

Stepdown .1
Fig. 17.

Step 18. Select **Linking Parameters** from the tree control and set:

Clearance plane .1

All Leads 0
Fig. 18.

Step 19. Click  in Opti Rough dialog box.

Step 20. Allow Mastercam to calculate the toolpath.




Fig. 17




Fig. 18





Fig. 19

C. Radial Toolpath.

Step 1. Use **Alt-T** to toggle off toolpath display.

Step 2. On the Toolpaths tab **TOOLPATHS** in the 3D group click **expand gallery** button and click

Radial  , Fig. 20.






Fig. 20

Step 3. Click the **surface** to select as Drive Surfaces and click **End Selection**  (ENTER), Fig. 5.

Step 4. Click **Containment Select** button  in the Toolpath/surface selection dialog box, Fig. 6.

Step 5. Select **C-plane** in the Chaining dialog box, Fig. 7.

Step 6. Click **Chain** button  in the Chaining dialog box, Fig. 7.

Step 7. Click a **line of top rectangle** to chain the top rectangle, Fig. 8. Click the OK button  in the Chaining dialog box.

Step 8. Click OK  in the Toolpath/surface selection dialog box, Fig. 9.




Fig. 21

Containment chain rectangle




Fig. 24




Fig. 22




Fig. 23




Fig. 25

Feed rate 80
Plunge rate 40
Fig. 26.

**Leave stock
on Drive walls
and floors
0**
Fig. 27.




Fig. 26




Fig. 27

Step 11. Select **Cut Parameters** from tree control and set:

Stepover .05

click the **Radial Point**



button

Fig. 28.

Click **Point** in graphics window

Fig. 29.




Fig. 28




Fig. 29

Step 12. Select **Tool containment** from tree control and set:

Compensate to Outside
Fig. 30.

Step 13. Select **Linking Parameters** from tree control and set:

Clearance plane .1

All leads 0
Fig. 31.




Fig. 30

Step 14. Click OK  in Radial dialog box.

Step 15. Save  (Ctrl-S).





Fig. 31

D. Contour Toolpath for Letters.

Step 1. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Contour**



Step 2. Click the **Polygon**  in Chaining dialog box, Fig. 32.

Step 3. Click a **selection polygon** around letters, **Fig. 33**. Press ENTER when done.

Click a polygon around letters

Step 4. Click **first letter** for **Approximate Start Point**, Fig. 33.

Step 5. Click OK  in Chaining dialog box.

Step 6. Select **Tool** from tree control and set:

Feed rate: 80
Plunge rate: 40
Fig. 34.




Fig. 33

Start point




Fig. 32




Fig. 34

Step 7. Select **Cut Parameters** from tree control and set:

Compensation type: Off
Fig. 35.

Step 8. Select **Lead In/Out** from tree control and:

Uncheck Lead In/Out
Fig. 36.




Fig. 35




Fig. 36

Step 9. Select **Linking Parameters** from tree control and set:

Uncheck **Clearance**

Check **Retract .1**

Depth -.02
Fig. 37.

Step 10. Click OK



Step 11. Save (Ctrl-S).




Fig. 37

E. Verify.

Step 1. Click **Toolpath Group-1** in the Toolpaths Manager to select **all three toolpaths**, **Fig. 38**.

Step 2. Click **Verify** in the Toolpaths Manager, **Fig. 38**.

Step 3. Click uncheck **Wireframe** in Mastercam Simulator home ribbon bar, **Fig. 39**.




Fig. 39

Step 4. Click **Play** (R) in VCR bar along bottom of the window.

Step 5. Note **Total Time** to run program under Toolpath Info in the Move List panel (**10min 28.05s**), **Fig. 42**.

Step 6. Switch back to Mastercam (Alt-Tab).




Fig. 40




Fig. 38

Move Info	
Toolpath Info	
Feed Length	747.976
Feed Time	10min 27.95s
Min/Max X	-0.067 / 1.868
Min/Max Y	-0.134 / 5.834
Min/Max Z	-0.297 / 0.200
Rapid Length	17.200
Rapid Time	0.1s
Total Length	765.176
Total Time	10min 28.05s
Verbose	

Fig. 41