


Jewelry Box Fixture


A. Sketch Fixture Rectangle.

Step 1. If necessary start a new Mastercam file, click **New**

 (**Ctrl-N**) on the Quick Access Toolbar QAT.



Step 2. On the Wireframe tab **WIREFRAME** click **Rectangle**



Step 3. In the Rectangle function panel:
under Dimensions, **Fig. 1**

Width 8

Height 10 and press ENTER

Press **O** key on keyboard to select AutoCursor **Origin** override,
Fig 2.

Click OK .





Fig. 1

Step 4. **Right click** the graphics window and click **Fit**  (**Alt-F1**).

B. Save As "FIXTURE"

Step 1. Click **Save As**  (**Ctrl-Shift-S**) on the Quick Access Toolbar QAT.


Step 2. Key-in **FIXTURE** for the filename and press ENTER.




 **Origin**

Fig. 2

C. Circles.

Step 1. On the Wireframe tab  click **Circle Center Point**



Step 2. In the Circle Center Point function panel:
under Size, **Fig. 3**

Click **Locked** 

Diameter .125 and press ENTER.




Fig. 3

Step 3. Press **spacebar** to activate AutoCursor **Fast Point**  and key-in coordinates shown below into the Fast Point. Press **ENTER** after keying-in coordinate. Continue and key-in each set of coordinates, **Fig. 4**.

Stock Screw Holes

.85, 1.1

7.15, 1.1

.85, 6.85

7.15, 6.85

Click **OK and Create New Operation**  or press ENTER twice.

Step 4. **Right click** in the graphics window and on the Mini Toolbar click **Wireframe Color**  drop down arrow and select **red**, **Fig. 5**.




Fig. 5




Fig. 4

Step 5. Key-in the X, Y coordinates into the **Fast Point** 

Base Screw Holes, Fig. 6

1.45, 2.7

7, 4

1.45, 5.3

press ENTER twice.




Fig. 6

Step 6. **Right click** in the graphics window and on the Mini Toolbar click **Wireframe Color**  drop down arrow and select **yellow**, **Fig. 7**.



Fig. 7

Step 7. Key-in the X, Y coordinates into the **Fast Point** 
Lid Screw Holes, Fig. 8
1.3, 1.9
4.1, 3.4
6.5, 1.9
1.5, 6.1
3.9, 4.6
6.7, 6.1
 press ENTER **twice**.




Fig. 8

Step 8. **Right click** in the graphics window and on the Mini Toolbar click **Wireframe Color**  drop down arrow and select **magenta**, **Fig. 9**.




Fig. 9

Step 9. Key-in the X, Y coordinates into the **Fast Point** 
Pin Holes, Fig. 10
3.5, .865
4.5, 7.135
 Click OK .

Step 10. Save  (**Ctrl-S**).

Tip:

Use Analyze Entity (**F4**) to confirm circle coordinates.

Tip:

Green Stock Screw Holes
 Red Base Screw Holes
 Yellow Lid Screw Holes
 Magenta Pin Holes






Fig. 10

D. Extrude Solid.

Step 1. Change to the Isometric View. **Right click** in the graphics window and click  **Isometric (WCS)** (Alt-7).

Step 2. On the Solids tab  click **Extrude** .

Step 3. Click Chain  in Chaining dialog box, **Fig. 11**.

Step 4. Click a **line of rectangle** to chain rectangle, **Fig. 12**.

Step 5. Click OK  in Chaining dialog box.

Step 6. In the Solid Extrude function panel:

under Operation, **Fig. 13**

select **Create body**

under Distance

Distance .75 and press ENTER

The direction arrow should **point down**, **Fig. 14**. If arrow points in wrong direction, click Reverse All , **Fig. 13**.

Click **OK** and **Create New Operation** .




Fig. 11




Fig. 12




Fig. 13




Fig. 14

E. Cut Pin Holes.

Step 1. Click Single  in Chaining dialog box, **Fig. 15**.

Step 2. Click **both Pin holes (magenta)** to chain, **Fig. 16**.

Step 3. Click OK  in Chaining dialog box.

Step 4. In the Solid Extrude function panel:

under Operation, **Fig. 17**

select **Cut Body**

under Distance

Distance .375 and press ENTER

The direction arrow should **point down**, **Fig. 18**. If arrow points in wrong direction, click Reverse All , **Fig. 17**.

Click **OK and Create New Operation** .




Fig. 15




Fig. 16




Fig. 18




Fig. 17

F. Cut Screw Holes.

Step 1. Click Polygon  in Chaining dialog box.

Step 2. Create a polygon selection around all circles except Pin holes, **Fig. 20**. To make the selection, click the positions 1 thru 6 to surround the all circles except Pin circles with a polygon. Try starting at Position 1 and working around. Double click or press ENTER to end selection.

Step 3. Click a circle for approximate start point and press ENTER, **Fig. 20**.

Step 4. Click OK  in Chaining dialog box.

Step 5. In the Solid Extrude function panel:
 under Operation, **Fig. 21**
 select **Cut Body**
 under Chains
 confirm **13 chains**
 under Distance
Distance .7 and press ENTER
 The direction arrow should **point down**, **Fig. 22**.
 Click OK .

Step 6. Save  (Ctrl-S).

Step 7. Use **Ctrl-T** to toggle **Translucency**.

Step 8. Change to Right View.
Right click in the graphics window and click  (Alt-5) to confirm the depth of holes, **Fig. 23**.




Fig. 20




Fig. 19




Fig. 22




Fig. 21



Fig. 23

G. Create TOP CUT WCS.

Step 1. Change to the Isometric View. **Right click** in the graphics window and click  **Isometric (WCS)** (Alt-7).

Step 2. Display the **Planes Manger** (Alt-L).

Step 3. In the Planes Manger:

Click **Create a new plane**  drop down and select **Relative to WCS > Top**, Fig. 24.

Step 4. In the New Plane dialog box:

Key-in **TOP CUT** for name, Fig. 25

Origin X 4

Origin Y 4

Origin Z 0

Click OK .




Fig. 24




Fig. 26




Fig. 25

H. Create **BOTTOM CUT WCS**.

Step 1. Back in the Planes Manger:

Click **Create a new plane**  drop down and select **Relative to WCS > Bottom**, Fig. 27.

Step 2. In the New Plane dialog box:

Key-in **BOTTOM CUT** for name, Fig. 28

Origin X -4

Origin Y 4

Origin Z .75

Click OK .

Step 3. Change to the Isometric View. **Right click** in the graphics window and click  **Isometric (WCS)** (Alt-7).

Step 4. Back in the Planes Manager:

Click **Set All** , Fig. 29.

Step 5. Save  (Ctrl-S).

Tip:

Click **Hide Levels Properties**  in the Planes Manager, Fig. 31.




Fig. 27




Fig. 28




Fig. 29




Fig. 30




Fig. 31

I. Create Bottom Cut Rectangle.

Step 1. **Right click** in the graphics window and on the Mini Toolbar click **Wireframe Color**  drop down arrow and select **green**, **Fig. 32**.






Fig. 32

Step 2. Use **Ctrl-T** to toggle **Translucency**.

Step 3. On the Wireframe tab  click **Rectangle** 

Step 4. In the Rectangle function panel:
under Settings, **Fig. 33**

Check **Anchor to center**

under Dimensions

Width 7

Height 7.25 and press ENTER

Press **O** key on keyboard to select AutoCursor **Origin** override,
Fig 34.

Click OK .




Fig. 33






Fig. 34

J. Extrude Cut Pocket.

Step 1. On the Solids tab  click **Extrude** .

Step 2. Click Chain  in Chaining dialog box.

Step 3. Click a **line of rectangle** to chain rectangle, **Fig. 35**.

Step 4. Click OK  in Chaining dialog box.

Step 5. In the Solid Extrude function panel:

under Operation, **Fig. 36**

select **Cut body**

under Distance

Distance .15 and press ENTER

The direction arrow should **point down**, **Fig. 37**. If arrow points in wrong direction, click Reverse All , **Fig. 36**.

Click OK .

Step 6. Save 
(Ctrl-S).




Fig. 35




Fig. 37





Fig. 36

K. Machine Type and Stock Setup.

Step 1. If necessary, display Toolpaths Manager. On the View tab



Step 2. If Machine Group is **not** displayed in the Toolpaths Manager,

Fig. 38 on the Machine tab **MACHINE**, click Machine **Mill** > Default from the menu.




Fig. 38

Step 3. Expand **Properties** (click +) in the Toolpaths Manager and click **Stock Setup** in the Toolpaths Manager, **Fig. 39**.

Step 4. Confirm Stock Plane is **BOTTOM CUT**, **Fig. 39**.

Step 5. Confirm **Display** is checked.

Step 6. Click **All Entities** button in the Stock Setup.

Step 7. Confirm X, Y and Z stock dimensions:
X 8
Y 10
Z .75

Step 8. Confirm Stock Origin coordinates:
X 0
Y 1
Z 0




Fig. 39

Step 9. Click OK  in the Machine Group Properties.




Fig. 40

L. Dynamic Mill Toolpath.

Step 1. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Dy-**



amic Mill




Fig. 41

Step 2. Click OK  in the NC name dialog, **Fig. 41**.

Step 3. Select **Machining regions**  button in Chain Options dialog box, **Fig. 42**.

Step 4. Select **Chain**  in Chaining dialog box, **Fig. 43**.

Step 5. Click a **line of rectangle** to Chain the rectangle and click OK  in Chain dialog box, **Fig. 44**.




Fig. 44

Step 6. Click OK  in Chain Options box, **Fig. 45**.




Fig. 42




Fig. 43




Fig. 45

Step 7. Select **Toolpath Type** from the tree control and confirm:

Dynamic Mill toolpath

Machining regions 1
Fig. 46.

Step 8. Select **Tool** from tree control and:
click **Select library tool**
Fig. 47.




Fig. 46




Fig. 47

Step 9. Click **Filter** button
Fig. 48.

Step 10. Click **None** button
under **Tool Types**
Fig. 49.

Step 11. Click **Endmill1 Flat** button
(first button top row) and
click OK
Fig. 49.

Step 12. Click **285 1/4 FLAT
ENDMILL** and click OK,
Fig. 50.




Fig. 48




Fig. 49




Fig. 50

Step 13. Back in **Tool** page set:

Feed rate 40
Plunge rate 20
Fig. 51.

Step 14. Select **Cut Parameters** from tree control and set:

Cutting method Climb

Stepover 45%

Stock to leave on walls and floors 0
Fig. 52.




Fig. 51




Fig. 52

Step 15. Select **Entry Motion** from tree control and set:

Plunge angle
10
Fig. 53.

Step 16. Select **Linking Parameters** from tree control and set:

Clearance 1
Depth -0.15
Fig. 54.

Step 17. Click OK  in Dynamic Mill dialog box.

Step 18. Allow Mastercam to calculate the toolpath.

Step 19. Save  (Ctrl-S).




Fig. 53




Fig. 54

M. Verify Dynamic Mill Toolpath.

- Step 1. Click **Verify**  in the Toolpaths Manager, **Fig. 55**.
- Step 2. Click **Play**  (R) in VCR bar along bottom of window.
- Step 3. Note **Total Time** to run program under Toolpath Info in the Move List panel (**roughly 13 minutes**), **Fig. 56**.
- Step 4. Switch back to Mastercam (**Alt-Tab**).




Fig. 57




Fig. 55




Fig. 56

N. Switch to TOP CUT WCS.

- Step 1. If necessary, use **Alt-T** to turn off toolpath display.
- Step 2. In the Planes Manger (**Alt-L**) set:
 under Name, **Fig. 58**
 Click **TOP CUT**
 Click **Set All** .
- Step 3. Change to the Isometric View. **Right click** in the graphics window and click  **Isometric (WCS)** (**Alt-7**).
- Step 4. Save  (**Ctrl-S**).




Fig. 58

0. FBM Drill Toolpath.

Step 1. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Expand gallery** button and click

FBM Drill



Fig. 59.




Fig. 59

Step 2. Select **Hole Detection** from the tree control and set:

Confirm:
Limit search to plane **Top**
Fig. 60.

Step 3. Select **Spot Drilling** from the tree control set:

Uncheck **Spot Drilling** check box
Fig. 61.




Fig. 60




Fig. 61

Step 4. Select **Pre-drilling** from the tree control set:

Uncheck **Pre-drilling** check box
Fig. 62.

Step 5. Click **Detect** button  at the top of the dialog box to detect the holes **Fig. 62.**

Step 6. Confirm:
15 holes
2 holes .375
depth
the others .6
depth.

Click **OK** 
Fig. 63.

Step 7. Save 
(Ctrl-S).




Fig. 62




Fig. 63

P. Backplot.

Step 1. Use **Ctrl-T** to toggle **Translucency**.

Step 2. In Toolpaths Manager click **FBM Drill** to select toolpath group, **Fig. 64**.

Step 3. Click **Backplot**  in Toolpaths Manager, **Fig. 64**.

Step 4. Turn on (button depressed) **Display tool**  and **Display rapid moves** , **Fig. 65**.

Step 5. Click **Play**  in the Backplot VCR bar.

Step 6. Click **OK**  to close Backplot.

Step 7. Use **Ctrl-T** to toggle **Translucency**.




Fig. 64




Fig. 65




Fig. 66