



Mastercam 2017 Chapter 16 Letters & Hole Toolpaths

A. Stock Setup.

- Step 1. If necessary, open your Letters file from Chapter 15.
- Step 2. Change to the Isometric View. **Right click** in the graphics window and click  **Isometric (WCS)** (Alt-7).
- Step 3. If necessary, display Toolpaths Manager. On the View tab  click  **Toolpaths** (Alt-O).
- Step 4. If Machine Group is **not** displayed in the Toolpaths Manager, **Fig. 1**, on the Machine tab , click Machine  >




Fig. 1

- Step 5. Expand **Properties** (click +) in the Toolpaths Manager, **Fig. 1**.
- Step 6. Click **Stock Setup** in the Toolpaths Manager, **Fig. 1**.
- Step 7. Click **left front top corner** of the stock to move the origin, **Fig. 2**. After you click corner the arrow will point to corner.
- Step 8. Click **All Entities box** button in the Stock Setup dialog box, **Fig. 2**.
- Step 9. Set **Z dimension .125**, **Fig. 2**.
- Step 10. Confirm **Display** check box is checked, **Fig. 2**.
- Step 11. Click OK  in Machine Group Properties, **Fig. 2**.




Fig. 2




Fig. 3

B. Contour Toolpath for Letters.

Step 1. Change to the Top View. **Right click** in the graphics window and click  **Top (WCS)** (Alt-1).

Step 2. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Con-**



Step 3. Click OK  in the NC name dialog, **Fig. 4**.

Step 4. Click the **Window**  in Chaining dialog box, **Fig. 5**.




Fig. 6

Step 5. Drag a selection around letters, **Fig. 6**.

Step 6. Click **first letter** for **Approximate Start Point**, **Fig. 6**.

Step 7. Click OK  in Chaining dialog box.

Step 8. Select **Tool** from tree control and set:

Feed rate: 15

Plunge rate: 7

Click **Select library tool**
Fig. 7.




Fig. 4




Fig. 5




Fig. 7

Step 9. Click **Filter**,
Fig. 8.

Step 10. Click **None**
under **Tool**
Types,
Fig. 9.

Step 11. Click **End-**
mill2 Sphere
(second button top row) and
click **OK**,
Fig. 9.

Step 12. Click **302 1/16 BALL**
ENDMILL and click **OK**
Fig. 10.




Fig. 8




Fig. 9




Fig. 10

Step 13. Select **Cut Parameters** from tree control and set:

Compensation type: Off
Fig. 11

Step 14. Select **Lead In/Out** from tree control and:

Uncheck Lead In/Out
Fig. 12.




Fig. 11




Fig. 12

Step 15. Select **Linking Parameters** from tree control and set:

Uncheck **Clearance**


Check **Retract .1 Absolute**

Depth -.02
Fig. 13.

Step 16. Click OK



Step 17. Change to the Isometric View.

Right click in the graphics window and click  **Isometric (WCS)** (Alt-7).

Step 18. Save  (Ctrl-S).




Fig. 13





Fig. 14

C. Toolpath For Hole.

Step 1. Use **Alt-T** to toggle toolpath display.

Step 2. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Contour**



Step 3. Click the **Single** in Chaining dialog box, **Fig. 15**.

Step 4. Click circle, **Fig. 16**.

Step 5. Click OK  in Chain dialog box.

Step 6. Select **Depth Cuts** from tree control and set:

Check **Depth cuts**

Max rough step: .03
Fig. 17.

Step 7. Select **Linking Parameters** from tree control and set:

Retract .1

Depth -.14
Fig. 18.

Step 8. Click OK .




Fig. 19




Fig. 16




Fig. 15




Fig. 17




Fig. 18

D. Verify.

Step 1. Click **Toolpath Group-1** in the Toolpaths Manager to select **both** toolpaths, **Fig. 20**.

Step 2. Click **Verify**  in the Toolpaths Manager, **Fig. 20**.

Step 3. Click **Verify**  in Mastercam Simulator home ribbon bar to select Verify mode and uncheck **Wireframe**, **Fig. 21**.




Fig. 21

Step 4. Click **Play**  (R) in VCR bar along bottom of the window, **Fig. 22**.



Fig. 22

Step 5. Note **Total Time** to run program under Toolpath Info in the Move List panel (**1min 33.38s**), **Fig. 24**.




Fig. 24

Step 6. Switch back to Mastercam (**Alt-Tab**).

Step 7. Save  (**Ctrl-S**).




Fig. 23