


Jewelry Box Lid




A. Sketch Lid Circle.

Step 1. If necessary start a new Mastercam file, click **New** (Ctrl-N) on the Quick Access Toolbar QAT.



Step 2. On the Wireframe tab **WIREFRAME** click **Circle Center Point**



Step 3. In the Circle Center Point function panel:

under Size, **Fig. 1**

Diameter 6.5 and press ENTER

Press **O** key on keyboard to select

AutoCursor **Origin** override,

Fig 2.

Click OK .

Step 4. **Right click** the graphics window and click **Fit** (Alt-F1).

Step 5. Use **F9** to toggle Origin/Axis display on and off to confirm Origin, **Fig. 2.**




Fig. 2




Fig. 1

B. Twin Edge Point Circles.

Step 1. On the Wireframe tab **WIREFRAME** click **Circle Edge Point** .

Step 2. Use the **upper quadrant** and **Origin** for the two points to sketch circle, **Fig. 3.**

Step 3. Repeat, and sketch second circle using **lower quadrant** and **Origin**, **Fig. 4.**

Step 3. Click OK in the Circle Edge Point function panel.




Fig. 3





Fig. 4


C. Save As “LID”

Step 1. Click **Save As**  (Ctrl-Shift-S) on the Quick Access Toolbar QAT.

Step 2. Key-in **LID** for the filename and press ENTER.

D. Trim Divide.

Step 1. On the Wireframe tab  click **Trim Break Extend**



Step 2. In the Trim Break Extend function panel:

under Type, **Fig. 5**
select **Divide/delete**
Trim arcs, **Fig. 6-9**.

Click OK  when done.




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9

E. Fillet.

Step 1. On the Wireframe tab **WIREFRAME** click **Fillet Entities**



Step 2. In the Fillet Entities function panel:
under Radius, **Fig. 10**

Radius .05

Click **both arcs at tip**, **Fig. 11**.

Click OK

Step 3. Save (Ctrl-S).




Fig. 11





Fig. 10

F. Extrude Solid.

Step 1. Change to the Isometric View.

Right click in the graphics window
and click **Isometric (WCS)** (Alt-7).

Step 2. On the Solids tab **SOLIDS** click **Extrude**



Step 3. Click Chain in Chain-
ing dialog box.

Step 4. Click **any geometry**, **Fig. 12**.

Step 5. Click OK in
Chaining dialog box.

Step 6. In the Solid Extrude
function panel:

under Operation, **Fig. 13**

select **Create body**

under Distance

Distance .75 and press ENTER

The direction arrow should **point down**, **Fig. 14**.

If arrow points in wrong direction, click Reverse All

, **Fig. 13**.

Click OK




Fig. 12




Fig. 13






Fig. 14

G. Create Vertical Line Down from Origin.

Step 1. Change to Front View. **Right click** in the graphics window and click  **Front** (Alt-2).

Step 2. **Right click** the graphics window and click **Fit**  (Alt-F1).

Step 3. Use **F9** to toggle Origin/Axis display on.

Step 4. On the Wireframe tab  click **Line Endpoints** .


Step 5. Sketch a vertical line down from the Origin, **Fig. 15**.



Fig. 15

H. Polar Arc.

Step 1. Use **Ctrl-T** to toggle **Translucency**.

Step 2. On the Wireframe tab  click **Arc Polar**  on **Circle Edge Point**  drop down.

Step 3. In the Arc Polar function panel:

under Size, **Fig. 16**

Radius 19

under Angle

Start angle 90

End angle 80 and press ENTER

Press **spacebar** to activate Fast Point 

Key-in **0, -19**  and press ENTER **twice**

Click OK .




Fig. 16





Fig. 17

I. Revolved Surface.

Step 1. On the Surfaces tab  click **Revolve** .

Step 2. Click Chain  in Chaining dialog box.

Step 3. Click **arc** for profile curve, **Fig. 18**.




Fig. 18

Step 4. Click OK  in Chaining dialog box.

Step 5. Click **vertical line** for axis of rotation, **Fig. 19**.




Fig. 19

Step 6. Click OK  in the Surface Revolve function panel, **Fig. 20**.






Fig. 20

J. Trim Solid.

Step 1. On the Solids tab  click **Trim to Surface/Sheet**  on **Trim by Plane**  drop down.

Step 2. Click **solid body below the surface** as body to trim, **Fig. 21**.

Step 3. Click **surface** as surface or sheet trim to, **Fig. 21**.

Step 4. Click OK  in Trim to Surface/Sheet function panel, **Fig. 22**.




Fig. 22




Fig. 21




Fig. 23

K. Move Geometry to New Level.

Step 1. Change to the Isometric View.

Right click in the graphics window and click  **Isometric (WCS)** (Alt-7).

Step 2. Use **Ctrl-A** to select all.

Step 3. Click the **solid** to **unselect**, Fig. 24.

Step 4. **Right click** in the graphics window and on the Mini Toolbar click **Change level**



Fig. 25.

Step 5. In the Change Levels dialog box:

under Operation, Fig. 26

select **Move**

under Level Number

Uncheck **Use Main Level**

Key-in **2** for Level Number

Click OK .

Step 6. In the Levels Manager (Alt-Z), Fig. 27

Key-in **GEOMETRY** in Level 2 Name

Click 1 in Number column to make Level active

Click to remove X in Visible column of **GEOMETRY** level to hide level.

Step 7. Save  (Ctrl-S).




Fig. 24

**Ctrl-A
then unselect
solid**




Fig. 25




Fig. 26




Fig. 27

L. Create **BOTTOM CUT WCS**.

Step 1. Use **Ctrl-T** to toggle **Translucency**.

Step 2. Display the **Planes Manger** (**Alt-L**).

Step 3. In the **Planes Manger**:

Click **Create a new plane**  drop down and select **Relative to WCS > Bottom**, **Fig. 28**.




Fig. 28

Step 4. In the **New Plane** dialog box:

Key-in **BOTTOM CUT** for name, **Fig. 29**

Origin X 0

Origin Y 0

Origin Z .75

Click **OK** .




Fig. 29

Step 5. Change to the **Isometric View**. **Right click** in the graphics window and click **Isometric (WCS)** (**Alt-7**).




Fig. 30

Step 6. Back in the **Planes Manager**:

Click **Set All** , **Fig. 30**.

Step 7. Save  (**Ctrl-S**).




Fig. 31

M. Pin Hole Circle.

Step 1. **Right click** in the graphics window and on the Mini Toolbar click **Wireframe Color**  drop down arrow and select **magenta**, Fig. 32.





Fig. 32

Step 2. On the Wireframe tab **WIREFRAME** click **Circle Center Point**



Step 3. In the Circle Center Point function panel:
under Size, Fig. 33

Diameter .125 and press ENTER

Key-in **0, 3.035**  in AutoCursor **Fast Point** and press ENTER twice.

Click OK .




Fig. 33

N. Cut Hole.

Step 1. On the Solids tab **SOLIDS** click



Extrude

Step 2. Click Chain  in Chaining dialog box.




Fig. 34

Step 3. Chain circle, Fig. 35.

Step 4. Click OK  in Chaining dialog box.

Step 5. In Extrude function panel, Fig. 36

Select

Cut Body

Select

Distance



Set

Distance .35

The direction arrow should **point down**.

Click OK




Fig. 35




Fig. 37




Fig. 36

O. Switch to TOP WCS.

- Step 1. In the Planes Manager (Alt-L):
 under Name, **Fig. 38**
 Click **Top**
 Click **Set All** .






Fig. 38


- Step 2. Change to Top View. **Right click** in the graphics window and click  (Alt-1).

- Step 3. Save  (Ctrl-S).

P. Translate Solid.

- Step 1. Use **F9** to toggle Origin/Axis display on.

- Step 2. On the Transform tab **TRANSFORM** click **Translate** .

- Step 3. Click the **solid body** to select it and click **End Selection**
 (ENTER), **Fig. 39**.

- Step 4. In Translate dialog box set:
 Select **Move**  **Fig. 40**
 **.5**
 **.1**
 Click **OK** .




Fig. 40

- Step 5. Click **Yes** to move defining wireframe entities, **Fig. 42**.




Fig. 42




Fig. 39






Fig. 41

Q. Rotate Solid.

Step 1. On the Transform tab **TRANSFORM** click **Rotate** .

Step 2. Click the **solid body** to select it and click **End Selection**  (ENTER), Fig. 43.

Step 3. In Rotate dialog box set:

Copy  Fig. 44

Number of Steps # 1

Rotation Angle  180

Click OK .

Step 4. **Right click** the graphics window and click

Clear Colors .

Step 5. Save 
(Ctrl-S).




Fig. 43




Fig. 45




Fig. 44




Fig. 46

R. Machine Type and Stock Setup.

Step 1. Change to the Isometric View. **Right click** in the graphics window and click  **Isometric (WCS)** (Alt-7).

Step 2. If necessary, display Toolpaths Manager. On the View tab  click  **Toolpaths** (Alt-O).





Fig. 47

Step 3. If Machine Group is **not** displayed in the Toolpaths Manager, **Fig. 47** on the Machine tab ,

click  **Mill** > Default from the menu.

Step 4. Expand **Properties** in the Toolpaths Manager and click **Stock Setup**, **Fig. 47**.

Step 5. Confirm Stock Plane is **Top**, **Fig. 48**.

Step 6. Confirm **Display** is checked.

Step 7. Key-in for X, Y and Z stock dimensions:

X 8
Y 8
Z .75

Step 8. Confirm Stock Origin coordinates:

X 0
Y 0
Z 0

Step 9. Click OK  in the Machine Group Properties.




Fig. 48





Fig. 49

S. Spiral Toolpath.

Step 1. On the Toolpaths tab **TOOLPATHS** in the 3D group click **expand gallery** button and click

Spiral , Fig. 50.




Fig. 50

Step 2. Click OK  in the NC name dialog, Fig. 51.





Fig. 51

Step 3. Click the **right solid body** to select as Drive Surfaces, Fig. 52. The solid will highlight when selected.

Step 4. Click **End Selection**  (ENTER).

Step 5. Click OK  in the Toolpath/surface selection dialog box, Fig. 53.




Fig. 52




Fig. 53

Step 6. Select **Toolpath Type** from the tree control and confirm:

Spiral toolpath
Drive surfaces
Fig. 54.




Fig. 54

Step 7. Select **Tool** from the tree control and:

Click **Select library tool** button
Fig. 55.

Step 8. Click **Filter** button
Fig. 56.

Step 9. Click **None** button under **Tool Types**
Fig. 56.

Step 10. Click **End-mill2 Sphere** button (second button top row) and click OK,
Fig. 57.




Fig. 55




Fig. 56




Fig. 57

Step 11. Click **307**
1/4 BALL
ENDMILL
and click
OK
Fig. 58.




Fig. 58

Step 12. Back in
Tool page
set:
Feed rate 40

Plunge rate 20
Fig. 59.




Fig. 59

Step 13. Select **Stock to leave** from tree control and set:

Stock to leave on Walls and Floors 0
Fig. 60.

Step 14. Select **Cut Parameters** from tree control and set:

Cut method One Way

Stepover .09

Click **Define Center Point**

Button 
Fig. 61.




Fig. 60




Fig. 61

Step 15. Click **geometry original Origin (intersection of the two circles)** in right Lid, **Fig. 62.**

Step 16. Back in **Cut Parameters** set:

Confirm **X .5 Y .1**

Outer radius 4.6

Keep tool down within 80%

Fig. 63.




Fig. 62




Fig. 63

Step 17. Select **Steep/ Shallow** from tree control and set:

Check **Use Z depths**
Minimum 0
Maximum -.3

Click **Apply**



Fig. 64.

Step 18. Select **Linking Parameters** from tree control and set:

Clearance plane .5

All Leads 0
Fig. 65.

Step 19. Click **OK**



in **Surface High Speed Toolpaths - Spiral** dialog box.

Step 20. Allow **Mastercam** to calculate tool-path.

Step 21. Save (Ctrl-S).




Fig. 64




Fig. 65

T. Verify Toolpath.

Step 1. Click **Verify**  in the Toolpaths Manager, **Fig. 67**.

Step 2. Click **Play**  (R) in VCR bar.

Step 3. Switch back to Mastercam (Alt-Tab).




Fig. 66




Fig. 68




Fig. 67

U. Copy Spiral Toolpath.

Step 1. Copy Spiral toolpath in the Toolpaths Manager. To copy, click to select toolpath, **Fig. 69**.

Then, use **Ctrl-C** and **Ctrl-V**, **Fig. 70**.

Step 2. Expand copied Surface High Speed Spiral toolpath and click **Parameters**, **Fig. 70**.

Step 3. Select **Toolpath type** from the tree control and:

Click **Remove selected drive surfaces**



Fig. 71.


Click **Drive Surfaces**



Fig. 71.

Click the **left Lid**, **Fig. 72**.

Click **End Selection**



(ENTER) to accept solid as drive surfaces.




Fig. 69




Fig. 70




Fig. 71




Fig. 72

Step 4. Select **Cut Parameters** from tree control and set:

Click **Define Center Point**



Fig. 73.

Click **geometry Origin** (intersection of the two circles) in left Lid

Confirm X **-0.5** Y **-0.1**

Fig. 75.

Step 5. Click **OK**  in Surface High Speed Toolpaths - Spiral dialog box.




Fig. 73




Fig. 74




Fig. 75


Step 6. In the Toolpaths Manager, click **Regenerate all selected operations** , Fig. 76.

Step 7. Save  (Ctrl-S).

V. Contour Toolpath.

Step 1. Use **Alt-T** to turn off toolpath display.

Step 2. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Contour**



Step 3. Click **Solids**  in Chaining dialog box and select **Loop** , Fig. 78.

Step 4. Click **bottom edge of right Lid solid**, Fig. 79. If the wrong edge is selected, click **Other face** in Pick Reference Face dialog box, Fig. 80. Click **OK**  in Pick Reference Face dialog box.

Step 5. The chain arrow should point **clockwise** around the chain, Fig. 81. If chaining directions arrow is pointing in the opposite direction - click **Reverse** , Fig. 78.






Fig. 76

Fig. 77



Chain loop

Fig. 79





Fig. 78



Chain arrow clockwise

Fig. 81



Fig. 80

Step 6. Click **bottom edge of left Lid solid**, **Fig. 82**. If the wrong edge is selected, click **Other face** in Pick Reference Face dialog box, **Fig. 83**. Click OK  in Pick Reference Face dialog box.





Fig. 82



Fig. 83

Step 7. The chain arrow should point **clockwise** around the chain, **Fig. 84**. If chaining directions arrow is pointing in the opposite direction - click Reverse ,




Fig. 84




Fig. 85

Step 8. Click OK  in Chaining dialog box, **Fig. 85**.

Step 9. In the 2D Toolpaths Contour dialog box confirm **2 Chains** are selected, **Fig. 86**.




Fig. 86

Step 10. Select **Tool** from the tree control and:

Click **Select library tool** button

Step 11. Use the Filter button to filter EndMill Flat and select **285 1/4 FLAT ENDMILL** and click OK,

Step 12. Select **Tool** from the tree control and set:

Feed rate 40

Plunge rate 20




Fig. 87




Fig. 88




Fig. 89

Step 13. Select **Cut Parameters** from tree control and set:

Compensation type Wear

Compensation direction Left

Tip comp: Tip

Stock to leave on Walls and Floors 0
Fig. 90.




Fig. 90

Step 14. Select **Depth Cuts** from tree control and set:

Check Depth cuts

Max rough step .2

Check Keep tool down
Fig. 91.




Fig. 91

Step 15. Select **Lead In/Out** from tree control and set:

Uncheck **Lead In/Out**
Fig. 92.

Step 16. Select **Break Through** from tree control and set:

Check **Break through**

Break through
amount .01
Fig. 93.




Fig. 92




Fig. 93

Step 17. Select **Linking Parameters** from tree control and set:

Depth 0
Fig. 94.

Step 18. Click OK .

Step 19. Save 
(Ctrl-S).

W. Verify Toolpaths.

Step 1. Click **Toolpath Group-1** in the Toolpaths Manager to select **all three toolpaths**, Fig. 95.

Step 2. Click **Verify**  in the Toolpaths Manager, Fig. 95.

Step 3. Click **Play**  (R) in VCR bar along bottom of the window.

Step 4. Note **Total Time** to run program under Toolpath Info in the Move List panel (**roughly 14.5 minutes**), Fig. 96.

Step 5. Switch back to Mastercam
(Alt-Tab).




Fig. 94




Fig. 95




Fig. 97

Move List	
Move Info	
Toolpath Info	
Feed Length	576.234
Feed Time	14min 30.37s
Min/Max X	-3.785 / 3.740
Min/Max Y	-3.475 / 3.475
Min/Max Z	-0.760 / 0.500
Rapid Length	364.757
Rapid Time	2.19s
Total Length	940.991
Total Time	14min 32.56s
Verbose	

Fig. 96

X. Switch to BOTTOM CUT WCS.

Step 1. If necessary, use **Alt-T** to turn off toolpath display.

Step 2. In the Planes Manger (**Alt-L**) set:

under Name, **Fig. 98**

Click **BOTTOM CUT**

Click Set All .




Fig. 98

Step 3. Change to the Isometric View. **Right click** in the graphics window and click  **Isometric (WCS)** (**Alt-7**).

Step 4. Save  (**Ctrl-S**).





Fig. 99

Y. FBM Drill Toolpath Right Lid.

Step 1. On the Toolpaths tab **TOOLPATHS** in the 2D group click **Expand gallery** button .

and click **FBM Drill** , Fig. 99.

Step 2. Click the **right Lid solid**, Fig. 100.

Step 3. Select **Hole Detection** from the tree control and set:

Uncheck **Limit search to plane**
Fig. 101.




Fig. 100




Fig. 101

Step 4. Select **Spot Drilling** from the tree control and uncheck **Spot Drilling** check box, **Fig. 102**.

Step 5. Select **Pre-drilling** from the tree control and uncheck **Pre-drilling** check box, **Fig. 103**.

Step 6. Click **Detect** button  at the top of the dialog box to find the holes, **Fig. 103**.




Fig. 102




Fig. 103

Step 7. Confirm 1 hole with depth of .35 is listed and click OK



Fig. 104.




Fig. 104





Fig. 105

Z. FBM Drill Toolpath Left Lid.

Step 1. On the Toolpaths tab **TOOLPATHS** in the 2D group click **FBM Drill**



Step 2. Click the **left Lid solid** and params are all set so just click **Detect** button , Fig. 106.




Fig. 106

Step 3. In the Toolpaths Manager **Ctrl** click both **FBM Drill Toolpath Groups** to select both Toolpath groups, Fig. 107.




Fig. 107

Step 4. Save  (Ctrl-S).




Fig. 108