




A. Set Level.

Step 1. If necessary start a new Mastercam file, click **New** (Ctrl-N) on the Quick Access Toolbar QAT.



Step 2. Display Level Manager. Use **Alt-Z**.

Step 3. In the Levels Manager:

Key-in **6** in the Number field, **Fig. 1**

Press **Tab** key to move to the Name Field and key-in **MOTOR MOUNT GEOMETRY**.





Fig. 1

B. Create Circle.

Step 1. Change to the **Front View**. Right click in the graphics window and click **Front** (Alt-2).




Step 2. Change the Z depth to **-7.45**. Right click in the graphics window and on the Mini Toolbar set **Z depth -7.45** and press ENTER, **Fig. 2**



Fig. 2

Step 3. On the Wireframe tab **WIREFRAME** click **Circle Center Point**



Step 4. In the Circle Center Point function panel: under Size, **Fig. 3**

Diameter 1 and press ENTER

Press **spacebar** to activate AutoCursor **Fast Point**



Key-in **1.5, 1.35** and press ENTER

Click OK




Fig. 3

Step 5. Right click the graphics window and click **Fit** (Alt-F1).



C. Save As "MOTOR MOUNT SOLID"

Step 1. Click **Save As** (Ctrl-Shift-S) on the Quick Access Toolbar QAT.



Step 2. Key-in **MOTOR MOUNT SOLID** for file name and press ENTER.





Fig. 4

D. Set Grid And Snap .05.

Step 1. On the View tab **VIEW** click **Show Grid** and **Snap to**



Step 2. Click the **Dialog Box Launcher** (Alt-G), **Fig. 5**.

Step 3. In the Grid Settings dialog box:
under Spacing, **Fig. 6**

X and Y Spacing .05

Click OK




Fig. 5





Fig. 6

E. Create Lines.

Step 1. On the Wireframe tab **WIREFRAME** click **Line Endpoints**



Step 2. Sketch the lines in **Fig. 7**

Use grid to determine location of lines.

Click OK





Fig. 7

F. Turn Off Grid and Snap.


Step 1. On the View tab **VIEW** click **Show Grid** and **Snap to**



Grid to unselect.

G. Trim Circle.

Step 1. On the Wireframe tab **WIREFRAME** click **Trim Break Extend**



Step 2. In the Trim Break Extend function panel:
under Type, **Fig. 8**

select **Divide/delete**

Trim circle to remove bottom.

Click circle at bottom, **Fig. 9**

Click OK




Fig. 8




Fig. 9

H. Fillet.

Step 1. On the Wireframe tab **WIREFRAME** click **Fillet Entities**



Step 2. In the Fillet Entities function panel:
under Radius, **Fig. 10**

Radius .03

Click Position 1 and Position 2
at **both corners**

Click OK




Fig. 11




Fig. 10

I. Offset Contour.

Step 1. On the Wireframe tab **WIREFRAME** click **Chains** on **Offset** drop

Step 2. Click Chain in the Chaining dialog box, **Fig. 12**.

Step 3. Click any geometry and click OK in Chaining dialog box, **Fig. 13**.

Step 4. In the Offset Contour dialog box:
under Mode, **Fig. 14**
select **Join**
under Distance

Distance **.01**

Click OK

Step 5. **Right click** the graphics window and click
Clear Colors




Fig. 12




Fig. 14




Fig. 13

Purple offset
on top




Fig. 15

J. Create Two Circles.

Step 1. Change to Top View. **Right click** in the graphics window and click  (Alt-1).


Step 2. **Fit**  (Alt-F1).

Step 3. Change the Z depth to **.85**. **Right click** in the graphics window and on the Mini Toolbar set **Z depth .85** and press ENTER, **Fig. 16**.



Fig. 16

Step 4. On the Wireframe tab  click **Circle Center Point**




Step 5. In the Circle Center Point function panel:
under Size, **Fig. 17**


Click **Locked** 

Diameter .08 and press ENTER

Press **spacebar** to activate AutoCursor **Fast Point** 

Key-in **.89, 7.7**  and press ENTER

Press **spacebar** to activate **Fast Point** 

Key-in **2.11, 7.7**  and press ENTER **twice**

Click OK 

(.89, 7.7, .85)

(2.11, 7.7, .85)




Fig. 17

Step 6. Save  (Ctrl-S).

K. Add Level.

Step 1. In the Levels Manager (Alt-Z):

Key-in **7** in the Number field, **Fig. 19**

Press **Tab** key to move to the Name Field and
key-in **MOTOR MOUNT SOLID**.

Fig. 18





Fig. 19

L. Extrude Solid.

Step 1. Change to the Isometric View. **Right click** in the graphics window and click



Step 2. Confirm **CPLANE:TOP** in Status bar at bottom of the graphics window, **Fig 20**.



Step 3. **Right click** in the graphics window and on the Mini Toolbar click **Solid Color** drop down arrow, then click **light cyan**, **Fig. 21**.





Fig. 21

Step 4. On the Solids tab **SOLIDS** click **Extrude**.



Step 5. Click Chain in Chaining dialog box, **Fig. 22**.



Step 6. Click **any motor mount geometry**, not the circles, **Fig. 23**.

Step 7. Click OK in Chaining dialog box.



Step 8. In the Solid Extrude function panel:

under Operation, **Fig. 24**

select **Create body**

under Distance

Distance .5

The direction arrow should **point to rear**, **Fig. 25**. If arrow points

in wrong direction, click Reverse All



Click **OK and Create New Operation**.




Fig. 22

Step 9. **Right click** the graphics window and click **Fit** (Alt-F1).



Chain Geometry




Fig. 23

Direction arrow




Fig. 25




Fig. 24

M. Cut Holes.

Step 1. Click Chain  in Chaining dialog box.

Step 2. Click **both circles** to chain, **Fig. 26**.

Step 3. Click OK  in Chaining dialog box.

Step 4. In the Solid Extrude function panel:

under Operation, **Fig. 27**

select **Cut Body**

under Distance

select **Through all**

The direction arrow should **point up**, **Fig. 28**. If arrow points in wrong direction, click Reverse All , **Fig. 27**.

Click OK .




Fig. 27




Fig. 26




Fig. 28

N. Turn Off Level.

Step 1. In the Levels Manager (**Alt-Z**):

Click to remove X in Visible column of **MOTOR MOUNT GEOMETRY** level to hide the level, **Fig. 29**.

Step 2. Save  (**Ctrl-S**).




Fig. 29

0. Chamfer Corners.

Step 1. Zoom-in on flange. Use **F1** and make a zoom window around flange, **Fig. 30**.


Step 2. On the Solids tab **SOLIDS** click **One Distance Cham-**



fer Step 3. In the Solid Selection dialog box, select **Edge** and unselect others, **Fig. 31**.



Fig. 30



Step 4. Click **both vertical corner edges**, **Fig. 32**.

Step 5. Use the arrow keys to pan over to the other flange, **Fig. 34**.

Step 6. Click **vertical corner edge** in front, **Fig. 34**.

Step 7. Click **From back**



in Solids Selection ribbon bar. **Fig. 33**.

Step 8. Click **vertical corner edge** in back, **Fig. 34**.

Step 9. Click OK  in Solid Selection dialog box.




Fig. 31




Fig. 33




Fig. 32




Fig. 34

Step 10. In the One Distance Chamfer function panel:
Confirm **4 edges** selected, **Fig. 35**
Distance .07
Click OK .

Step 11. Save  (**Ctrl-S**).




Fig. 36




Fig. 35