

Fusion 360 V2 to Mastercam 2020

A. Open File in Mastercam 2020.

Step 1. In Fusion, export your **Body** file as IGES file. The file is saved in the Download folder and requires no cloud translation.

Step 2. In Mastercam 2020, click File Menu > Open .

Step 3. In the Open dialog box set **Files of type** to **IGES Files**, navigate to the Download folder, select your **BODY** file and click Open, **Fig. 1**.

Step 4. Change to the Isometric View. **Right click** in the graphics window and click  **Isometric (WCS)** (**Alt-7**).





Fig. 1

B. Confirm Metric Units.

Step 1. In the bottom right corner of the display confirm units are **Metric**, **Fig. 2**.

C. Save Your File.

Step 1. **Save As**  (**Ctrl-Shift-S**).

Step 2. Key-in **RAIL BODY FORM** for the filename, change to **Mastercam Parts** folder and Save.

Tip: The IGES file comes in Mastercam as all surfaces. We will add curves to edge at rear to be able to select the cartridge hole, then convert to solid.




Fig. 2

12/21/19

D. Rotate Body Around Axes.

Step 1. Confirm **TOP CPLANE** and **3D Construction Mode** in Status bar at bottom of graphics window, **Fig 3**.



Fig. 3

Step 2. On the Transform tab **Transform** click **Rotate**



Step 3. Use **Ctrl-A** to select all, **Fig 4**. The surfaces will highlight when selected. Click **End Selection** **End Selection** (ENTER).

Step 4. In the Rotate function panel:
 under Method, **Fig. 5**
 Select **Move** 
Number 1
Angle 90 and press **Tab** key
 Click **OK** and **Create**
New Operation 

Ctrl-A
to select all



Fig. 4




Fig. 5

Fig. 6

Step 5. Click **CPLANE** in Status bar at bottom of the graphics window and click **Left** from the menu, **Fig 7**.





Fig. 7

Step 6. Use **Ctrl-A** to select all **again** and click **End Selection** **End Selection** (ENTER)



Step 7. In the Rotate function panel:
 under Method, **Fig. 8**
 Select **Move** 
Angle -90 and press **Tab**
 Click **OK** 




Fig. 8

Fig. 9

Step 8. **Right click** the graphics window and click **Fit**  (Alt-F1).

Step 9. **Right click** the graphics window and click **Clear Colors** 

Step 10. Save  (Ctrl-S).



E. Curve on Edges.

Step 1. **Right click** in the graphics window and from the menu click GView > **Isometric Reverse (WCS)**.

Step 2. On the Wireframe tab click Curve All Edges



Step 3. In the Curve On All Edges function panel:

Click **inside cylindrical surface of cartridge hole, Fig. 11**

Click **End Selection** (ENTER)

Click OK




Fig. 11




Fig. 12






Fig. 10

F. Move to Origin.

Step 1. Display the Origin. Use **F9** to toggle axes, **Fig. 13**.

Step 2. On the Transform tab **Transform** click **Move to Origin**




Step 3. Press the **C** key on keyboard to configure Auto Cursor behavior of your cursor to snap to **Arc Center**, **Fig. 14**.



Fig. 14

Step 4. Click **curve at rear edge of cartridge hole** as point to translate from, **Fig. 15**.




Step 5. **Right click** the graphics window and click **Fit** (**Alt-F1**).



Step 6. **Right click** the graphics window and click **Clear Colors**.




Step 7. Confirm **center of cartridge hole at rear of car** as new position of Origin, **Fig. 16**.




Step 8. Save  (**Ctrl-S**).

G. Confirm Origin.

Step 1. **Right click** in the graphics window and from the menu click **GView > Left (WCS)**.




Step 2. Confirm Origin is in **center of cartridge hole**, **Fig. 17**.



H. Surfaces Into Solid.


Step 1. Change to the Isometric View. **Right click** in the graphics window and click




Step 2. **Right click** the graphics window and click **Fit**  (Alt-F1).

Step 3. Toggle axes off. Use **F9**.

Step 4. On the Solids tab  click **From Surfaces**



Step 5. Use **Ctrl-A** to select all, **Fig 18**. Click **End Selection**  (ENTER).

Step 6. In the From Surfaces function panel set:
under Selection, **Fig. 19**
confirm **13 surfaces**
under Original surface
select **Delete**

Click OK .

Ctrl-A
to select all

Fig. 18





Fig. 19

I. Create Check Solid.

Step 1. On the Solids tab  click **Block** .

Step 2. In the Primitive Block function panel:
under Type, **Fig. 20**
Solid
under Origin
select **Center**
under Dimensions
Length 40
Width 50
Height -2
under Axis
X
under Direction
Selected side
Click **most forward vertex** of body, **Fig. 21**.
Click OK .

Step 3. Save  (Ctrl-S).





Fig. 21

Fig. 20




Fig. 22

J. Create WCS LEFT CUT Plane.

Step 1. Toggle axes on. Use F9.

Step 2. Display the Planes Manager. Use Alt-L.

Step 3. In the Planes Manager:

Click **Create a new plane**  drop down and select **Relative to WCS > Top**, Fig. 23.




Fig. 23

Step 4. In the New Plane function panel:

Key-in **LEFT CUT** for name, Fig. 24

Origin X 0

Origin Y 0

Origin Z 34

Click OK .




Fig. 24

Step 5. Back in the Planes Manager:

Click **Set All** , Fig. 25.




Fig. 25

Step 6. Confirm LEFT CUT Origin, Fig. 26.

Step 7. Save  (Ctrl-S).




Fig. 26