


HST Toolpaths for Rail Car Body

Cut Body (HST Hybrid)



A. Machine Type and Stock Setup.

Step 1. If necessary, open your file from Chapter 20.

Step 2. If necessary, display Operations Manager. Use **Alt-O**.

Step 3. If Machine Group is **not** displayed in the Operations Manager, **Fig. 1**, click MACHINE TYPE Menu > Mill > Default.

Step 4. Expand **Properties** (click the +) in the Toolpaths Manager, **Fig. 1**.

Step 5. Click **Stock Setup** in the Toolpaths Manager.




Fig. 1

Step 6. Confirm Stock View is **Top**, **Fig. 2**.

Step 7. Click the **left front top corner of the stock** to move the origin. After you click corner the arrow will point to corner.

Step 8. Key-in X, Y and Z stock dimension into the fields

X 305
Y 70
Z 42

Step 9. Key-in Stock Origin coordinates:

X 0
Y -36
Z 21





Fig. 2

Step 10. Click OK  in Machine Group Properties. The Stock is displayed as red wireframe, **Fig. 3**.

B. Confirm WCS LEFT CUT.

Step 1. In bottom left corner of display, confirm Tool Plane (T/Cplane) is **LEFT CUT**, **Fig. 3**.

Step 2. Confirm **Left Cut Origin**. Use **F9** to toggle axes.




Fig. 3

C. Left Cut Finish Hybrid Toolpath.

Step 1. Click TOOLPATHS Menu > Surface High Speed > Hybrid.

Step 2. Click OK  in NC name dialog, Fig. 4.




Fig. 4

Step 3. Click the **solid car body** to select as Drive Surfaces, Fig. 5. The solid will highlight when selected.





Fig. 5

Step 4. Click **End Selection**  (ENTER) in ribbon bar to accept solid as drive surfaces.

Step 5. Click **Check Select** button  in the Toolpath/surface selection dialog box, Fig. 6.

Step 6. Click the **solid check body**, Fig. 7.







Fig. 7

Step 7. Click **Activate solid selection** button  in the Solids selection ribbon bar and click **Select face**  and unselect **Select body** , Fig. 8.




Fig. 6

Step 8. Click VIEW Menu > Orient > **Flip X for Y**.




Fig. 8

Step 9. Click the **flat face on the underside of Body and flat face at rear**, Fig. 9.





Fig. 9

Step 10. Click **End Selection**  (ENTER) in ribbon bar to accept solid bodies and faces as check surfaces.




Fig. 10

Step 11. Click OK  in the Toolpath/surface selection dialog box, Fig. 10.

Step 12. Select **Toolpath Type** from the tree control and confirm: **Hybrid tool-path Drive and Check surfaces** Fig. 11.

Step 13. Select **Tool** from tree control and:
Click **Select library tool** Fig. 12.




Fig. 11




Fig. 12

Step 14. Click **Filter** button, **Fig. 13.**




Fig. 13

Step 15. Click **None** button under **Tool Types**, **Fig. 14.**




Fig. 14

Step 16. Click **491 BALL END-MILL 6mm** and click **OK**, **Fig. 15.**




Fig. 15

Step 18. Back in Tool page set:

Feed rate 300

Plunge rate 200

Fig. 16.

Step 19. Select **Cut Parameters** from tree control and set:
Open contour direction Zigzag

Z stepdown 3

Limiting angle 34

3D stepover 1.2

Check **Preserve Z passes**

Offset method Upper to lower

Keep tool down within 80%

Stock to leave on walls and floors 0
Fig. 17.




Fig. 16




Fig. 17

Step 20. Select **Steep/ Shallow** from tree control and set:

Check **Use Z depths**
Minimum 0
Maximum -37

Click **Apply**



Fig. 18.




Fig. 18

Step 21. Select **Linking Parameters** from tree control and set:

Clearance plane 2

select **Minimum Vertical Retract**

Part clearance 4

All Leads 0
Fig. 19.




Fig. 19

Step 22. Select **Arc Filter/Tolerance** from tree control and set:

Total tolerance .0625

check **Line/Arc Filtering Settings**

uncheck **Create arcs in XY**

check **One way filtering**

set **Minimum arc radius .0625**

Cut tolerance 10%
Fig. 20.




Fig. 20

Step 23. Click OK  in Hybrid dialog box and allow Mastercam to calculate toolpath .

Step 24. Save  (Alt-F S).





Fig. 21

D. Verify Left Cut.

Step 1. In the Toolpaths Manager, click the toolpath to select and click **Verify** , Fig. 22.

Step 2. Click **Play**  (R) in VCR bar, Fig. 23.

Step 3. Note **Total Time** to run program (38min 57.19s), Fig. 24.

Step 4. Switch back to Mastercam (Alt-Tab).




Fig. 22

Move List	
Move Info	
Toolpath Info	
Feed Length	11664.439
Feed Time	39min 55.7s
Min/Max X	-1.324 / 258.685
Min/Max Y	-19.933 / 37.439
Min/Max Z	-37.000 / 2.000
Rapid Length	2486.738
Rapid Time	1.49s
Total Length	14151.177
Total Time	39min 57.19s
Verbose	

Fig. 24




Fig. 25

E. Mirror LEFT CUT to RIGHT CUT Toolpath.

Step 1. Change to Isometric View  (Alt-7).

Step 2. Click TOOLPATHS Menu > Transform.

Step 3. Under Type, select **Mirror**, Fig. 26.

Step 4. Under Source, select **NCI**, Fig. 26.

Step 5. Under Source operations, select **Surface High Speed (Hybrid)**, Fig. 26.

Step 6. Click the **Mirror** tab at the top of the dialog box, Fig. 26.






Fig. 26

Step 7. Under Method, select **Mirror about X axis** , Fig. 27.

Step 8. Click OK  in Transform Operation Params dialog box.

Step 9. Allow Mastercam to calculate toolpath.

Step 10. Save  (Alt-F S).





Fig. 27

F. Verify Right Cut.

Step 1. In Toolpaths Manager, click the **Transform/Mirror** toolpath, Fig. 28.

Step 2. Click **Verify**  in Toolpaths Manager, Fig. 28.

Step 3. Click **Play**  (R) in VCR bar.

Step 4. Click **Close**  to close Mastercam Simulation.

Step 5. Save  (Alt-F S).




Fig. 28




Fig. 29