


Skateboard Deck Hardware

A. Open Board Assembly.

Step 1. If necessary, Open your BOARD ASSEMBLY file.

Step 2. Rotate view to view **underside of deck and the four bolt holes a base-plate** as shown in **Fig. 1**. Hold down middle mouse button (wheel) and drag.

Step 3. Use the **Zoom to Area**  in the View toolbar to drag a zoom window around a **truck assembly**, **Fig. 1**.




Fig. 1

B. Enable Toolbox Browser.

Step 1. If necessary, click Tools Menu > Add-Ins.

Step 2. Check **SolidWorks Toolbox Browser** to place a check in the check box, then click OK, **Fig. 2**.





Fig. 2

C. Toolbox Machine Screw Countersunk.

Step 1. Click the **Design Library** tab  in the Task Pane (right side of drawing area), **Fig. 3**.




Fig. 3


Step 2. Expand the **Toolbox**  **Toolbox**

Expand **Ansi Metric** folder  **Ansi Metric**

Expand **Bolts and Screws** folder  **Bolts and Screws**

Click **Machine Screw (Countersunk)** folder  **Machine Screws (Countersunk)**

Step 3. In the lower pane, click **Flat Head Screw**, **Fig. 3** and drag screw into drawing along side the deck as shown in **Fig. 4**.

Step 4. In **Size popup dialog**, set **Size** to **M4**, **Fig. 4** and click OK .

Step 5. Click **Cancel**  when done.









Fig. 4

D. Toolbox Nut.

Step 1. Click the **Design Library** tab  in the Task Pane, **Fig. 5**.

Step 2. In the **Toolbox**  **Toolbox**
 Expand **Ansi Metric** folder 
 Expand **Nuts** folder 
 Click **Hex Nuts** folder 

Step 3. In the lower pane, click **Hex Jam Nut B18.2.3.5M**, **Fig. 5** and drag to shank of screw. While dragging, position tip your cursor on shank of screw, **Fig. 6**. When nut snaps into place on the screw and pointer (cursor) changes to Concentric mate , release the nut.

Step 4. In **Size popup dialog**, set **Size** to **M5** and click OK .

Step 5. Click **Cancel**  when done.

Step 6. Save. Use **Ctrl-S**.







Fig. 5

E. Distance Mates.




Step 1. If necessary, slide the nut onto the screw as shown in **Fig. 7**.

Step 2. Click **Rotate Component**  on the Assembly toolbar. **Rotate Component** is in the **Move Component**  flyout . Or Tools Menu > Component > Rotate.

Step 3. Rotate screw slightly to view **flat top face of screw head**, **Fig. 7**.

Step 4. Click **Mate**  on the Assembly toolbar.

Step 5. Click **flat top face of screw head** and **flat top face of nut**, **Fig. 7**.

Step 6. Click **Distance**  in Mate pop-up, **Fig. 8**. Set **distance** to **16.5** and press ENTER. Click **Add/Finish Mate**  to add Distance mate. Click **OK**  in the Property Manager when done, **Fig. 9**. Save, use **Ctrl-S**.




Fig. 6




Fig. 7



Fig. 8




Fig. 9

F. Insert New Sub-Assembly.

Step 1. **Right click BOARD ASSEMBLY** at the top of Feature Manager and click **Insert New Sub-assembly** from menu, **Fig. 10**.





Fig. 10

Step 2. **Rename new Assem1** in the Feature Manager, **Fig. 11**. To rename, click **Assem1** name in Feature Manager and press **F2** on keyboard. Key-in **SCREW AND NUT ASSEMBLY**.

Rename: **Assem1** to **SCREW AND NUT ASSEMBLY**

Step 3. Drag the **Flat Head Screw** down into new **SCREW AND NUT ASSEMBLY**, **Fig. 13**. To drag part into assembly, grab the Flat Head Screw in the Feature Manager and drag over the Screw

and Nut Assembly, when your cursor changes to  release the screw.

Step 4. **Repeat and drag the Hex Nut** into new **SCREW AND NUT ASSEMBLY**, **Fig. 14**.




Fig. 11




Fig. 12

**Rename
SCREW AND NUT ASSEMBLY**




Fig. 13




Fig. 14

G. Add Sub-Assembly with Mates.

Step 1. **Ctrl drag** new **SCREW AND NUT ASSEMBLY** out of the Feature Manager and place in drawing area next to original, **Fig. 15**. To **Ctrl drag**, hold down **Ctrl** key and drag **SCREW AND NUT ASSEMBLY** from Feature Manager.




Fig. 15

As you mate each new **SCREW AND NUT ASSEMBLY** to the baseplate holes, keep the original **ASSEMBLY** in the drawing area. Always drag the first **ASSEMBLY** out of the Feature Manager. This will assure each new **ASSEMBLY** will be orientated in position to grab the nut edge which will be used for mate.





Fig. 16

Step 2. **Alt drag** cylindrical edge of underside of nut to edge of bolt hole in baseplate, **Fig. 16**. When assembly snaps into place and pointer (cursor) changes to Concentric mate  release assembly. Try slightly spinning assembly in the hole to check correct mate.




Fig. 17

Step 3. **Repeat Steps 1 and 2** for each hole in baseplates. Always **Ctrl drag** first **SCREW AND NUT ASSEMBLY** in Feature Manager and place in drawing area next to original. Keep original **ASSEMBLY** in the drawing area to assure correct orientation for mate. Then, **Alt drag** cylindrical edge of underside of nut to edge of bolt hole in baseplate for Mate.




Fig. 18

Step 4. Save. Use **Ctrl-S**.