

Chair Top Rail

A. 3D Sketch.

Step 1. If necessary, open your CHAIR file.

Step 2. Click **Isometric**  on the Standard Views toolbar. (**Ctrl-7**)

Step 3. Zoom in around **top of back leg**, Fig. 1. To zoom, place the cursor over the top of back leg area and spin the wheel on mouse back. While spinning the wheel keep cursor on the area.




Step 4. Click **3D Sketch**  on the Weldments toolbar.

Step 5. Click **Line**  (L) on the Sketch toolbar.

Step 6. Press Tab to change sketch plane to **YZ** plane  . View

the Reference Triad  at bottom left corner of display to determine sketch plane.




Step 7. Sketch a line from outside rear corner of leg, Fig. 2.

Step 8. **Right click graphics area and click Select** from menu to unselect Line Tool.

Step 9. **Ctrl click the outside top edge of leg body** and line to select both. Release Ctrl key and click **Make Collinear**  on the context toolbar, Fig. 3.

Step 10. Click **Smart Dimension**  (S) on the Sketch toolbar.



Step 11. Dimension line **.25**, Fig. 4.




Fig. 3




Fig. 4

2/23/18

Step 12. Click Line  (L) on the Sketch toolbar.

Step 13. Press Tab to change sketch plane to XY plane 

Step 14. Sketch a line from **left to right** away from short line, **Fig. 5**. To sketch line on X axis, click away from short line at approximately Position 1 to start line. Move cursor across sketch along X

axis, when cursor changes to  (yellow X) click, Position 2.





Fig. 5

Step 15. Click Smart Dimension  (S) on the Sketch toolbar.

Step 16. Dimension line 23.25, Fig. 6.

Step 17. **Right click graphics area and click Select** from menu to unselect Smart Dimension.




Fig. 6

Step 18. **Ctrl click endpoint of short line and long line. Release Ctrl key and click Make Coincident ** on the context toolbar, Fig. 7.




Fig. 7

Step 19. Click Smart Dimension  (S) on the Sketch toolbar.

Step 20. Add 1.5 dimension, Fig. 8. Before adding dimension, you might have to zoom out, use Z key, and drag left endpoint out to left.




Fig. 8

Step 21. Click Zoom to Fit  (F) on the View toolbar.


Step 22. Click 3D Sketch  on the Weldments toolbar to exit 3D Sketch.



Fig. 9

B. Structural Member.

Step 1. Click Trimetric  on the Standard Views toolbar.

Step 2. Click Structural Member  on the Weldments toolbar.


Step 3. In the Structural Member Property Manager set:
under Standard, Fig. 10

My Profiles

under Type:
Chair Wood

under Size:
2 x 6

click long line in 3D sketch, Fig. 11
under Settings



Rotation Angle  334°
press Tab key, Fig. 12
click OK .




Fig. 10




Fig. 11





Fig. 12

C. Rename Structural Member6 TOP RAIL.

Step 1. Rename Chair Wood 2 X 6(1) to TOP RAIL in the Feature Manager, Fig. 13.

Step 2. Hide 3DSketch7. To hide, click 3DSketch7 in the Feature Manager and click **Hide**  on the context toolbar, Fig. 13.




D. Extruded Cut.

Step 1. Click **top face** of Top Rail member and click **Sketch**  on the context toolbar, Fig. 14.

Step 2. Click **Normal To**




on the Standard Views toolbar. (**Ctrl-8**)



Step 3. Click **3 Point Arc**  (S) in the **Arc flyout**  on the Sketch toolbar.

Step 4. Sketch 3 Point Arc across Top Rail, Fig. 15.

Step 5. Click **Smart Dimension**



(S) on the Sketch toolbar.

Step 6. Dimension both 4.5s first, then arc 45.5, Fig. 15.




Fig. 15




Fig. 13

Step 7. Click **Extruded Cut** [Extruded Cut] on the Weldments toolbar.

Step 8. In the Cut-Extrude Property Manager set:
under Direction 1, **Fig. 16**

End Condition **Through All**

The Direction arrow should point towards area to be cut away,
Fig. 17. If arrow is pointing in wrong direction, check **Flip side to cut**, **Fig. 16**.

under Feature Scope

unselect **Auto-select**

click **Top Rail**, **Fig. 17**

click OK ✓.

Step 9. Save. Use **Ctrl-S**.




Fig. 17




Fig. 16

E. Hole Wizard Counterbore.

Step 1. Click **Hole Wizard**  on the Weldments toolbar.

Step 2. In the Property Manager, on the Type tab set:
under Hole Type, **Fig. 18**

select **Counterbore** 

under Standard:

select **ANSI Inch**

under Size:

select **#8**

under End Condition:

Through All

under Options

check **Under head countersink**

Under Head Countersink  **Diameter .33**

under Feature Scope, **Fig. 18**

unselect **Auto-select**

click **Top Rail**, **Fig. 19**

Step 3. Click **Positions tab**  at top of Property Manager.

Step 4. Click top face one time as face for holes. Then, click twice to place two holes inside right edge, **Fig. 20**.

Step 5. Right click graphics area and click **Select** from menu to unselect Point tool.




Fig. 18




Fig. 19






Fig. 20

Step 6. **Ctrl click both Points** to select both. Release Ctrl key and click **Make Vertical**  on the context toolbar, Fig. 21.




Step 7. Click **Smart Dimension**  (S) on the Sketch toolbar.




Step 8. Add dimensions, Fig. 22.

Step 9. Click **Centerline**  (S) on the Sketch toolbar.




Step 10. Sketch a vertical centerline down from Origin , Fig. 23.

Step 11. Right click graphics area and click **Select** from menu to unselect Centerline tool.




Step 12. Drag a selection around all geometry, Fig. 24.



Step 13. Click **Mirror**  on the Features toolbar, Fig. 25.

Step 14. Click **OK**  in the Hole Wizard Property Manager.



Step 15. Save. Use **Ctrl-S**.